STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL

# TRAILER MAINTENANCE & SAFETY INSPECTION

CHP 108 (Rev. 6-05) OPI 052

* Inspection of these items meets the minimum requirements of 34505.5 CVC

CARRIER NAME: GSR | UNIT #: 3RM13 | LICENSE #: 4N Z45942 | YEAR: 2013 | MAKE: RSCUS

| | | MILEAGE 8-5-20 | | MILEAGE 9-24-20 | | MILEAGE 4-15-21 | | MILEAGE 7-24-21 | | MILEAGE 10-6-21 | | MILEAGE 1-21-22 | | MILEAGE 5-17-22 | | MILEAGE 8-11-22 | | MILEAGE | | MILEAGE | | MILEAGE | | MILEAGE | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | OK | DEF | OK | DEF | OK | DEF | OK | DEF | OK | DEF | OK | DEF | OK | DEF | OK | DEF | OK | DEF | OK | DEF | OK | DEF | OK | DEF |
| | 1. All lights, signals, reflectors | / | | / | | / | | / | | / | | / | | / | | / | | | | | | | | | |
| | 2. Mudflaps | / | | / | | / | | / | | / | | / | | / | | / | | | | | | | | | |
| * | 3. Air leaks-brake system | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | | | | | | | | |
| * | 4. Air leaks-dump system | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | | | | | | | | |
| | 5. Frame, subframe, and body-cracks | / | | / | | / | | / | | / | | / | | / | | / | | | | | | | | | |
| * | 6. Brake adjustment | / | | / | | / | | / | | / | | / | | / | | / | | | | | | | | | |
| * | 7. Brake system, drums, and components-condition | / | | / | | / | | / | | / | | / | | / | | / | | | | | | | | | |
| * | 8. Suspension system-springs, shackles, u-bolts, and/or torque rods | / | | / | | / | | / | | / | | / | | / | | / | | | | | | | | | |
| * | 9. Connecting device-kingpin, drawbar, eye and/or safety devices | / | | / | | / | | / | | / | | / | | / | | / | | | | | | | | | |
| * | 10. Fifth wheel on pull trailer | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | | | | | | | | |
| * | 11. Air hoses and tubing-leaks, condition, and/or protection | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | | | | | | | | |
| * | 12. Tires-tread depth, inflation, and condition | / | | / | | / | | / | | / | | / | | / | | / | | | | | | | | | |
| * | 13. Wheels, lug nuts, and studs-cracks, looseness, and/or condition | / | | / | | / | | / | | / | | / | | / | | / | | | | | | | | | |
| * | 14. Hoses and tubing-condition, protection | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | | | | | | | | |
| * | 15. Hydraulic Master cylinder-level, leaks, and/or condition | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | | | | | | | | |
| * | 16. Parking brake-able to hold the vehicle | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | | | | | | | | |
| * | 17. Emergency breakaway brake system | / | | / | | / | | / | | / | | / | | / | | / | | | | | | | | | |
| * | 18. Air relay valves and tank-mounting | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | | | | | | | | |
| * | 19. Brakes release after complete loss of service air | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | N/A | | | | | | | | | |
| * | 20. Wheel seals-leaks and/or condition | / | | / | | / | | / | | / | | / | | / | | / | | | | | | | | | |
| * | 21. Under carriage-clean and secure | / | | / | | / | | / | | / | | / | | / | | / | | | | | | | | | |

Ungers Mobile Fleet Service
32681 Wagon Wheel Rd.
Agua Dulce, CA 91390
661-618-6123

VIN 1R9BT3936DR608242

746088

## SIGNATURES OF INSPECTORS

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| DATE 8-8-20 | | DATE 9-24-20 | | DATE 4-15-21 | | DATE 7-24-21 | |
| DATE 10-6-21 | | DATE 1-21-22 | | DATE 5-17-22 | | DATE 8-11-22 | |
| DATE | | DATE | | DATE | | DATE | |

Form may be reproduced privately—bulk supplies are not available from the CHP