

TRAILER MAINTENANCE & SAFETY INSPECTION

CHP 108 (Rev. 6-05) OPI 062

* Inspection of these items meets the minimum requirements of 34505.5 CVC

CARRIER NAME: **GSR** UNIT #: **M50P2** MILEAGE: **1-18-21** **4-27-21** **7-13-21** **11-5-21** **8-25-22**

YEAR: **2011** MAKE: **RS** LICENSE #: **4K45028**

ITEM	1-18-21		4-27-21		7-13-21		11-5-21		8-25-22									
	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF
1. All lights, signals, reflectors	/	/	/	/	/	/	/	/	/	/								
2. Mudflaps	/	/	/	/	/	/	/	/	/	/								
* 3. Air leaks-brake system	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
4. Air leaks-dump system	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
5. Frame, subframe, and body-cracks	/	/	/	/	/	/	/	/	/	/								
* 6. Brake adjustment	/	/	/	/	/	/	/	/	/	/								
* 7. Brake system, drums, and components-condition	/	/	/	/	/	/	/	/	/	/								
* 8. Suspension system-springs, shackles, u-bolts, and/or torque rods	/	/	/	/	/	/	/	/	/	/								
* 9. Connecting device-kingpin, drawbar, eye and/or safety devices	/	/	/	/	/	/	/	/	/	/								
* 10. Fifth wheel on pull trailer	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
* 11. Air hoses and tubing-leaks, condition, and/or protection	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
* 12. Tires-tread depth, inflation, and condition	/	/	/	/	/	/	/	/	/	/								
* 13. Wheels, lug nuts, and studs-cracks, looseness, and/or condition	/	/	/	/	/	/	/	/	/	/								
* 14. Hoses and tubing-condition, protection	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
* 15. Hydraulic Master cylinder-level, leaks, and/or condition	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
* 16. Parking brake-able to hold the vehicle	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
* 17. Emergency breakaway brake system	/	/	/	/	/	/	/	/	/	/								
* 18. Air relay valves and tank-mounting	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
* 19. Brakes release after complete loss of service air	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A								
* 20. Wheel seals-leaks and/or condition	/	/	/	/	/	/	/	/	/	/								
* 21. Under carriage-clean and secure	/	/	/	/	/	/	/	/	/	/								

Ungers Mobile Fleet Service
32681 Wagon Wheel Rd.
Agua Dulce, CA 91390
661-618-6123

R9BT3931BR608275

SIGNATURES OF INSPECTORS

 7585Q	DATE	 7651	DATE	 7496	DATE	 7-13-21	DATE
	DATE		DATE		DATE		DATE
	DATE		DATE		DATE		DATE