

Lic # 4UB1823

BSR 303

BIT 90-Day Mechanical Inspection

~~MC STUDIO RENTALS~~

Carrier: Three Amigos

Date: 1/21/24

Mileage: N/A

Vehicle ID: 2R9BC40309MR772092

Problem:

Repair Story:

Problem:

Repair Story:

PARTS

Problem:

Repair Story:

Problem:

Repair Story:

Problem:

Repair Story:

Problem:

Repair Story:

* Not Required for 90-day Inspection **Full Service/BIT 90-day Mechanical Inspection**

* Not Required for 90-day Inspection		Full Service/BIT 90-day Mechanical Inspection			
* Oil level at arrival	tr	Steering Wheel Lash & Mounts		Rims, Lugs & Dual Mating	✓
* Change Oil		Parking Brake & Clutch Free Play		Wires & Hoses - Rubbing or Chaffing	✓
* R&R Oil, Fuel, & H2O Filters		Battery Condition		General Engine & Accessory Leaks	NA
* Air Cleaner		Tire Condition	✓	Box/Bed, Latches, Hinges, Rollers	NA
Coolant		Radiator Condition, Hoses, Leaks		Mud Flaps	NA
P/W Steering Fluid		Belts, Fans, Pumps & Mounts		Air Gauges & Low Warning 55-75 psi	NA
Brake Fluid		Brake adj., Lining, Drums & Rotors	✓	Emergency Dual Stopping	NA
Transmission Fluid		Air / Hydraulic Brake Lines & Valves		Air Loss Test - Applied	✓
Differential & Hubs	✓	King Pins, Steering Arm/Ties & Shocks		Air Loss Test - Unapplied	✓
Washer Solution		Spring Retainers, U-bolts & Leafs	✓	Tractor Protection	✓
* Lube Chassis	✓	Hangers, Torque Arms & Equalizers	✓	Brake Away Brake	✓
Lights & Reflectors	✓	U-joints, Carriers & Wheel Seals	✓	Air Brake Can, Rod Nut & Cleaves Pins	NA
Windshield & Mirrors		Frame, Frame Bolts & Cross Members	✓	Air Tank Mounts & Drained	NA
Windshield Wipers & Operation		Engine & Transmission Mounts		Emergency/Service Lines & Rubbers	NA
Horn, Defroster, Warning Devices		Lift gate, Motor & Condition	NA	Fifth Wheel, Pintle Hook & Hitches	✓
Oil, Water, Temp & Charging Gauges		Fuel Tank Mounts, Lines & Fittings		Fifth Wheel Pin	NA
Reflector Box & Fire Extinguisher		Exhaust System		7-Way Cord & Receptacle	✓

Repairs Still Needed!

[Signature]
Mechanic's Signature