

TRAILER MAINTENANCE & SAFETY INSPECTION

CHP 108 (Rev. 6-05) OPI 062


* Inspection of these items meets the minimum requirements of 34505.5 CVC

CARRIER NAME		UNIT #	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	
YEAR	MAKE	LICENSE #	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF
THREE AMIGOS		WRS	9-17-24													
2018	NAPP	4PX3529	/													
	1. All lights, signals, reflectors		/													
	2. Mudflaps		/													
	* 3. Air leaks-brake system		NA													
	4. Air leaks-dump system		NA													
	5. Frame, subframe, and body-cracks		/													
	* 6. Brake adjustment		/													
	* 7. Brake system, drums, and components-condition		/													
	* 8. Suspension system-springs, shackles, u-bolts, and/or torque rods		/													
	* 9. Connecting device-kingpin, drawbar, eye and/or safety devices		/													
	* 10. Fifth wheel on pull trailer		NA													
	* 11. Air hoses and tubing-leaks, condition, and/or protection		NA													
	* 12. Tires-tread depth, inflation, and condition		/													
	* 13. Wheels, lug nuts, and studs-cracks, looseness, and/or condition		/													
	* 14. Hoses and tubing-condition, protection		NA													
	* 15. Hydraulic Master cylinder-level, leaks, and/or condition		NA													
	* 16. Parking brake-able to hold the vehicle		NA													
	* 17. Emergency breakaway brake system		/													
	* 18. Air relay valves and tank-mounting		NA													
	* 19. Brakes release after complete loss of service air		NA													
	* 20. Wheel seals-leaks and/or condition		NA													
	* 21. Under carriage-clean and secure		/													

Ungers Mobile Fleet Service
32681 Wagon Wheel Rd.
Agua Dulce, CA 91390
661-618-6123

IN 9603433JA44207

SIGNATURES OF INSPECTORS

	DATE 9-17-24	DATE	DATE	DATE
	DATE	DATE	DATE	DATE
	DATE	DATE	DATE	DATE

WRS