

STATE OF CALIFORNIA
DEPARTMENT OF CALIFORNIA HIGHWAY PATROL
TRAILER MAINTENANCE & SAFETY INSPECTION

CHP 108 (Rev. 6-05) OPI 082

* Inspection of these items meets the minimum requirements of 34508.5CVC

CARRIER NAME		UNIT #	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	
THREE AMIGOS		WR2		10102												
YEAR	MAKE	LICENSE #	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF
2015	ELINATOR	4N14158														
1. All lights, signals, reflectors			/	/												
2. Mudflaps			/	/												
3. Air leaks-brake system			NA	NA												
4. Air leaks-dump system			NA	NA												
5. Frame, subframe, and body cracks			/	/												
6. Brake adjustment			/	/												
7. Brake system, drums, and components condition			/	/												
8. Suspension system-springs, shackles, u-bolts, and/or torque rods			/	/												
9. Connecting device-knipin, drawbar, eye and/or safety devices			/	/												
10. Fifth wheel on pull trailer			NA	NA												
11. Air hoses and tubing-leaks, condition, and/or protection			NA	NA												
12. Tires-tread depth, inflation, and condition			/	/												
13. Wheels, lug nuts, and studs-cracks, looseness, and/or condition			/	/												
14. Hoses and tubing-condition, protection			/	/												
15. Hydraulic Master cylinder-level, leaks, and/or condition			NA	NA												
16. Parking brake-able to hold the vehicle			NA	NA												
17. Emergency breakaway brake system			/	/												
18. Air relay valves and tank-mounting			NA	NA												
19. Brakes release after complete loss of service air			NA	NA												
20. Wheel seals-leaks and/or condition			/	/												
21. Under carriage-clean and secure			/	/												

Ungers Mobile Fleet Service
32681 Wagon Wheel Rd.
Agua Dulce, CA 91390
661-618-6123

1E9EW3435CA442015

SIGNATURES OF INSPECTORS

DATE 11-12-25	DATE 11-12-25	DATE	DATE
DATE	DATE	DATE	DATE
DATE	DATE	DATE	DATE

WR2