

Lic # 4UB6802 GSR 311

**BIT 90-Day Mechanical Inspection**

**MC STUDIO RENTALS**

Carrier: Three Amigos

Date: 11/21/24

Mileage: N/A

Vehicle ID: 2R9BL4038NR772097

Problem:

Repair Story:

Problem:

Repair Story:

**PARTS**

Problem:

Repair Story:

Problem:

Repair Story:

Problem:

Repair Story:

Problem:

Repair Story:

**\* Not Required for 90-day Inspection Full Service/BIT 90-day Mechanical Inspection**

* Oil level at arrival	
* Change Oil	
* R&R Oil, Fuel, & H2O Filters	
* Air Cleaner	
Coolant	
P/W Steering Fluid	
Brake Fluid	
Transmission Fluid	
Differential & Hubs	✓
Washer Solution	✓
* Lube Chassis	✓
Lights & Reflectors	✓
Windshield & Mirrors	
Windshield Wipers & Operation	
Horn, Defroster, Warning Devices	
Oil, Water, Temp & Charging Gauges	
Reflector Box & Fire Extinguisher	

Steering Wheel Lash & Mounts	
Parking Brake & Clutch Free Play	
Battery Condition	
Tire Condition	✓
Radiator Condition, Hoses, Leaks	
Belts, Fans, Pumps & Mounts	
Brake adj., Lining, Drums & Rotors	✓
Air / Hydraulic Brake Lines & Valves	✓
King Pins, Steering Arm/Ties & Shocks	
Spring Retainers, U-bolts & Leafs	✓
Hangers, Torque Arms & Equalizers	✓
U-joints, Carriers & Wheel Seals	✓
Frame, Frame Bolts & Cross Members	✓
Engine & Transmission Mounts	
Lift gate, Motor & Condition	NA
Fuel Tank Mounts, Lines & Fittings	
Exhaust System	

Rims, Lugs & Dual Mating	✓
Wires & Hoses - Rubbing or Chaffing	✓
General Engine & Accessory Leaks	NA
Box/Bed, Latches, Hinges, Rollers	✓
Mud Flaps	NA
Air Gauges & Low Warning 55-75 psi	
Emergency Dual Stopping	NA
Air Loss Test - Applied	
Air Loss Test - Unapplied	
Tractor Protection	✓
Brake Away Brake	✓
Air Brake Can, Rod Nut & Cleaves Pins	NA
Air Tank Mounts & Drained	NA
Emergency/Service Lines & Rubbers	NA
Fifth Wheel, Pintle Hook & Hitches	✓
Fifth Wheel Pin	NA
7-Way Cord & Receptacle	✓

**Repairs Still Needed!**

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_  
Mechanic's Signature