

TRAILER MAINTENANCE & SAFETY INSPECTION

* Inspection of these items meets the minimum requirements of 34505.5 CVC

CHP 108 (Rev. 6-05) OPI 062

CARRIER NAME		UNIT #	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	
YEAR		MAKE	LICENSE #	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF
22		R45	4445717	300	7-1-22	3-17-25	3-25-24								
	1.	All lights, signals, reflectors		/		/		/							
	2.	Mudflaps		/		/		/							
*	3.	Air leaks-brake system		N/A		N/A		N/A							
	4.	Air leaks-dump system		N/A		N/A		N/A							
	5.	Frame, subframe, and body-cracks		/		/		/							
*	6.	Brake adjustment		/		/		/							
*	7.	Brake system, drums, and components-condition		/		/		/							
*	8.	Suspension system-springs, shackles, u-bolts, and/or torque rods		/		/		/							
*	9.	Connecting device-kingpin, drawbar, eye and/or safety devices		/		/		/							
*	10.	Fifth wheel on pull trailer		N/A		N/A		N/A							
*	11.	Air hoses and tubing-leaks, condition, and/or protection		N/A		N/A		N/A							
*	12.	Tires-tread depth, inflation, and condition		/		/		/							
*	13.	Wheels, lug nuts, and studs-cracks, looseness, and/or condition		/		/		/							
*	14.	Hoses and tubing-condition, protection		N/A		N/A		N/A							
*	15.	Hydraulic Master cylinder-level, leaks, and/or condition		N/A		N/A		N/A							
*	16.	Parking brake-able to hold the vehicle		N/A		N/A		N/A							
*	17.	Emergency breakaway brake system		/		/		/							
*	18.	Air relay valves and tank-mounting		N/A		N/A		N/A							
*	19.	Brakes release after complete loss of service air		N/A		N/A		N/A							
*	20.	Wheel seals-leaks and/or condition		/		/		/							
*	21.	Under carriage-clean and secure		/		/		/							

Ungers Mobile Fleet Service
32681 Wagon Wheel Rd.
Agua Dulce, CA 91390
661-618-6123

SIGNATURES OF INSPECTORS

VN 1R9BCH035NR772042	DATE	DATE	DATE	DATE
	7-1-22			
	3-17-25			
	3-25-24			