

TRAILER MAINTENANCE & SAFETY INSPECTION

* Inspection of these items meets the minimum requirements of 34505.5 CVC

CHP 108 (REV. 6-05) OPI 062

CARRIER NAME

7 HEE AMIGOS

UNIT #

300

MILEAGE

12,823

MILEAGE

MILEAGE

MILEAGE

MILEAGE

MILEAGE

MILEAGE

MILEAGE

MILEAGE

MILEAGE

MILEAGE

MILEAGE

YEAR MAKE

2021 RS

LICENSE #

4LVM4L681

OK DEF

OK DEF

OK DEF

OK DEF

OK DEF

OK DEF

OK DEF

OK DEF

OK DEF

OK DEF

OK DEF

OK DEF

1. All lights, signals, reflectors	/																			
2. Mudflaps	/																			
3. Air leaks-brake system	N/A																			
4. Air leaks-dump system	N/A																			
5. Frame, subframe, and body-cracks	/																			
6. Brake adjustment	/																			
7. Brake system, drums, and components-condition	/																			
8. Suspension system-springs, shackles, u-bolts, and/or torque rods	/																			
9. Connecting device-kingpin, drawbar, eye and/or safety devices	/																			
10. Fifth wheel on pull trailer	N/A																			
11. Air hoses and tubing-leaks, condition, and/or protection	N/A																			
12. Tires-tread depth, inflation, and condition	/																			
13. Wheels, lug nuts, and studs-cracks, looseness, and/or condition	N/A																			
14. Hoses and tubing-condition, protection	N/A																			
15. Hydraulic Master cylinder-level, leaks, and/or condition	N/A																			
16. Parking brake-able to hold the vehicle	/																			
17. Emergency breakaway brake system	N/A																			
18. Air relay valves and tank-mounting	N/A																			
19. Brakes release after complete loss of service air	N/A																			
20. Wheel seals-leaks and/or condition	/																			
21. Under carriage-clean and secure	/																			

Ungers Mobile Fleet Service
32681 Wagon Wheel Rd.
Agua Dulce, CA 91390
661-618-6123

SIGNATURES OF INSPECTORS

DATE	DATE	DATE	DATE	DATE	DATE	DATE	DATE	DATE	DATE	DATE