

# TRAILER MAINTENANCE & SAFETY INSPECTION

CHP 103 (Rev. 6-05) OPI 062

\* Inspection of these items meets the minimum requirements of 34505.5 CVC

CARRIER NAME		UNIT #	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	MILEAGE	
THREE AMIGOS		4	3-25-25													
YEAR	MAKE	LICENSE #	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF	OK	DEF
2018	NAPP	4RD9672														
1. All lights, signals, reflectors			/													
2. Mudflaps			/													
* 3. Air leaks-brake system			N/A													
4. Air leaks-dump system			N/A													
5. Frame, subframe, and body-cracks			/													
* 6. Brake adjustment			/													
* 7. Brake system, drums, and components-condition			/													
* 8. Suspension system-springs, shackles, u-bolts, and/or torque rods			/													
* 9. Connecting device-kingpin, drawbar, eye and/or safety devices			/													
* 10. Fifth wheel on pull trailer			N/A													
* 11. Air hoses and tubing-leaks, condition, and/or protection			N/A													
* 12. Tires-tread depth, inflation, and condition			/													
* 13. Wheels, lug nuts, and studs-cracks, looseness, and/or condition			/													
* 14. Hoses and tubing-condition, protection			N/A													
* 15. Hydraulic Master cylinder-level, leaks, and/or condition			N/A													
* 16. Parking brake-able to hold the vehicle			N/A													
* 17. Emergency breakaway brake system			/													
* 18. Air relay valves and tank-mounting			N/A													
* 19. Brakes release after complete loss of service air			N/A													
* 20. Wheel seals-leaks and/or condition			/													
* 21. Under carriage-clean and secure			/													

Ungers Mobile Fleet Service  
32681 Wagon Wheel Rd.  
Agua Dulce, CA 91390  
661-618-6123

LN9EU3437JA442009

## SIGNATURES OF INSPECTORS

DATE	DATE	DATE	DATE
3-25-25			
DATE	DATE	DATE	DATE
DATE	DATE	DATE	DATE