

# ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD		
REPORT NUMBER	FLEET UNIT NUMBER	DATE
15	6SR 308	11/21/24

Vin # 1R9BC4035NR772042

MOTOR CARRIER OPERATOR Three Amigos	INSPECTOR'S NAME (PRINT OR TYPE) Justin McClain
ADDRESS 34855 Petersen Rd	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE Santa Clarita CA 91390	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input checked="" type="checkbox"/> LIC. PLATE NO. <input type="checkbox"/> VIN <input type="checkbox"/> OTHER 4UU5717
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

## VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			<b>1. BRAKE SYSTEM</b>	NA			e. Pitman Arm
NA			a. Service Brakes				f. Power Steering
NA			b. Parking Brake System				g. Ball and Socket Joints
NA			c. Brake Drums or Rotors				h. Tie Rods and Drag Links
NA			d. Brake Hose				i. Nuts
NA			e. Brake Tubing				j. Steering System
NA			f. Low Pressure Warning Device				<b>8. SUSPENSION</b>
NA			g. Tractor Protection Valve	✓			a. Axle Positioning Parts
NA			h. Air Compressor	✓			b. Spring Assembly
NA			i. Electric Brakes	✓			c. Torque, Radius or Tracking Components
NA			j. Hydraulic Brakes				<b>9. FRAME</b>
NA			k. Vacuum Systems	✓			a. Frame Members
NA			l. Antilock Brake System	✓			b. Tire and Wheel Clearance
NA			m. Automatic Brake Adjusters	NA			c. Adjustable Axle Assemblies (Sliding Subframes)
			<b>2. COUPLING DEVICES</b>				<b>10. TIRES</b>
NA			a. Fifth Wheels	NA			a. Steer-Axle Tires
NA			b. Pintle Hooks	NA			b. All Other Tires
NA			c. Drawbar/Towbar Eye	✓			c. Speed-Restricted Tires
NA			d. Drawbar/Towbar Tongue	✓			<b>11. WHEELS AND RIMS</b>
NA			e. Safety Devices	✓			a. Lock or Side Ring
NA			f. Saddle-Mounts	✓			b. Wheels and Rims
			<b>3. EXHAUST SYSTEM</b>				c. Fasteners
NA			a. No leaks forward of/directly below the driver/sleeper compartment.	✓			d. Welds
NA			b. Bus: No leaking/discharging in violation of standard.	NA			<b>12. WINDSHIELD GLAZING</b>
NA			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	NA			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			<b>4. FUEL SYSTEM</b>	NA			<b>13. WINDSHIELD WIPERS</b>
NA			a. No visible leak.	NA			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
NA			b. Fuel Tank Filler Cap	NA			<b>14. MOTORCOACH SEATS</b>
NA			c. Fuel tank securely attached.	NA			Any passenger seat that is not securely fastened to the vehicle structure.
			<b>5. LIGHTING DEVICES</b>				<b>15. REAR IMPACT GUARD</b>
NA			All lighting devices and reflectors required by Section 393 shall be operable.	NA			In place, securely attached, proper size, proper placement (see 393.86).
			<b>6. SAFE LOADING</b>				<b>16. OTHER</b>
NA			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	NA			List any other condition(s) which may prevent safe operation of this vehicle.
NA			b. Front End Structure				
NA			c. Intermodal Container Securement Devices				
			<b>7. STEERING MECHANISM</b>				
NA			a. Steering Wheel Free Play				
NA			b. Steering Column				
NA			c. Front Axle Beam/All Other Steering Components				
NA			d. Steering Gear Box				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION:  OK,  NEEDS REPAIR,  NA IF ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.