RECORD OF ANNUAL INSPECTION

(49 CFR 396.17-23)

Prepare Separate Report for Each Vehicle Inspected

DATE

| COMPANY NAME | _ | VEHICLE TYPE CONVERTER | | | | | | | | | |
|--|-----------|------------------------|--------------------|---------|-----------|-------------------------------------|-----------|----------------|-------------------------|--------|--------|
| THREEHMIGOS | | | | | | ☐ TRUCK ☐ TRACTOR 🖟 TRAILER ☐ DOLLY | | | | | |
| THLEEAMIGOS STREET ADDRESS 28523 SHANIA PL | | | | | | VEHICLE MAKE | E | VAN 0 | | | 22 |
| CITY | | STATE | | ZIP | | VEHICLE IDEN | TIFICATIO | N (Compan | y No., State Tag No. or | VIN) | |
| SAUGUS | | CA | | 1136 | 0 | 309 | | CA | 4023 | 15 | 2 |
| INSPECTOR'S NAME | E (Please | Print) | | | À | | E | MPLOYEE I | NO. | | |
| DANUNG | | | | 001 | | | | | | | |
| REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Part 396, Appendix A) | | | | | | | | | | | |
| To the | OK | REPAIR | | OK | REPAIR | | ОК | REPAIR | | OK | REPAIR |
| BRAKES | | | EXHAUST | | | STEERING | | | FRAME | | |
| Adjustment | 1 | | Leaks | 1 | | Adjustment | | | Members | 1 | |
| Mechan. Compon. | | | Placement | 1 | | Column/Gear | | | Clearance | / | |
| Drum/Rotor | | | LIGHTING | | | Axle | 1 | | Rear Impact Guard | | |
| Hose/Tubing | / | | Headlights | | | Linkage | / | | TIRES | | |
| Lining | | | Tail/Stop | 1 | | Power Steering | | | Tread | 1 | |
| Antilock System | | | Clearance/Marker | 1 | | Other | | | Inflation | 7, | - |
| Automatic Adjusters | | | Identification | 1 | | FUEL SYSTEM | | | Damage | / | |
| Low Air Warning | | | Reflectors | 7 | | Tank(s)/Cap(s) | 1 | | Speed Restrictions | | |
| Trailer Air Supply | | | Other | | | Lines | 1 | | Other | | |
| Compressor | | | | | | | | | | | |
| Parking Brakes ` | | | CAB/BODY | | | SUSPENSION | | | WHEELS/RIM | | |
| Other | | | Access | / | | Springs | / | | Fasteners | 1. | |
| | | | Eqpt./Load Secure | 1 | | Attachments | 1/ | | Disc/Spoke | / | |
| COUPLERS | | | Tie-Downs | /. | | Sliders | 1 | | | | |
| Fifth-Wheel & Mount | | | Headerboard | | | | | | WINDSHIELD | | |
| Pin/Upper Plate | | | Motorcoach Seats | | | MIRRORS | | | Glass | | |
| Pintle-Hook/Eye | 1 | | Other | | | | | | Wipers | | |
| Safety Chain(s) | / | | | | | | | | | | |
| DELIA DICO | | | | \ | | | | | | | |
| REMARKS | | | | | | | | | | | |
| | | | | | | | | | | | |
| Certification | : This ve | ehicle has | passed all the ins | pection | items for | the annual vehicle | | | ordance with 49 Cl | R Pari | 396. |
| QUALIFIED INS | SPECTOR | 'S SIGNATU | | | | | D | ATE 8 - | 1-25 | | |