

DATE

12-18-23

RECORD OF ANNUAL INSPECTION

(49 CFR, 396. 17-23)

Prepare Separate Report for Each Vehicle Inspected

D7156608

COMPANY NAME THREE AMIGOS			VEHICLE TYPE <input type="checkbox"/> TRUCK <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> CONVERTER <input type="checkbox"/> DOLLY		
STREET ADDRESS 28523 SHANA PL			VEHICLE MAKE HIS	MODEL VAN	YEAR 2021
CITY SAUGUS	STATE CA	ZIP 91350	VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN) 306 CA 4UN4681		
INSPECTOR'S NAME (Please Print) DANUNGEA				EMPLOYEE NO. 001	

REPORT OF CONDITION (For Detailed Information on Inspection Procedures see FMCSR Section 396, Appendix G)

	OK	REPAIR		OK	REPAIR		OK	REPAIR		OK	REPAIR
BRAKES			EXHAUST			STEERING			FRAME		
Adjustment			Leaks			Adjustment			Members		
Mechan. Compon.			Placement			Column/Gear			Clearance		
Drum/Rotor			LIGHTING			Axle			TIRES		
Hose/Tubing			Headlights			Linkage			Tread		
Lining			Tail/Stop			Power Steering			Inflation		
Antilock System			Clearance/Marker			Other			Damage		
Automatic Adjusters			Identification			FUEL SYSTEM			Speed Restrictions		
Low Air Warning			Reflectors			Tank(s)			Other		
Trailer Air Supply			Other			Lines					
Compressor											
Parking Brakes			CAB/BODY			SUSPENSION			WHEELS/RIM		
Other			Access			Springs			Fasteners		
			Eqpt./Load Secure			Attachments			Disc/Spoke		
COUPLERS			Tie-Downs			Sliders			WINDSHIELD		
Fifth-Wheel & Mount			Headerboard						WINDSHLD. WIP.		
Pin/Upper Plate			Motorcoach Seats			MIRRORS					
Pintle-Hook/Eye			Other								
Safety Chain(s)											

REMARKS

Certification: This vehicle has passed all the inspection items for the annual vehicle inspection in accordance with 49 CFR Part 396.

QUALIFIED INSPECTOR'S SIGNATURE



DATE

12-18-23